



Stadhuis

Time of Inspection: 2025-06-18 14:33

📍 Stadhuisplein, Eindhoven

👤 Inspector Name:
P1Meter.nl

🕒 Time of House Construction:
1975


🏠 House Space:
400m²

💰 Detection Cost:
EUR 350


Woonkamer

	No problem	repair	replace	Remark
General	✓			Prima
General(1)		🔧		repair

Photos



General



General

Inspector Signature

P. J. Miller

House Owner Signature

V